



Technical drawing of a high-speed steel drill bit. The drawing shows the bit with dimensions labeled A, H, J, K, and E. Dimension A is the diameter of the main body. Dimension H is the length of the main body. Dimension J is the length of the flute. Dimension K is the length of the cutting edge. Dimension E is the diameter of the cutting edge.

- Swageless rope termination allows the swivel to be field-installed without expensive tools or complicated processes.
- Ultimate strength exceeds the rated Safe Working Load (SWL).
- Built with high-strength alloy steel and zinc-plated for corrosion resistance.

|                                  |                         |
|----------------------------------|-------------------------|
| <b>Material</b>                  | Zinc Plated Alloy Steel |
| <b>Termination Type</b>          | Swageless               |
| <b>Connector Type</b>            | Eye                     |
| <b>Water Pressure Resistance</b> | Moderate                |

| Rope Size (In) | Part No. | SWL Pounds (3:1) | SWL Pounds (5:1) | Dim A  | Dim E   | Dim H   | Dim J - Hole Dia. | Dim K   | Overall Length |
|----------------|----------|------------------|------------------|--------|---------|---------|-------------------|---------|----------------|
| 1/8            | 6312     | 2300             | 1380             | 7/8    | 1/4     | 3/8     | 1/4               | 3/8     | 3-7/8          |
| 1/4            | 6325     | 5000             | 3000             | 1-1/4  | 5/16    | 1/2     | 3/8               | 7/16    | 5-7/8          |
| 3/8            | 6337     | 8000             | 4800             | 1-1/2  | 1/2     | 23/32   | 5/8               | 5/8     | 6-13/16        |
| 1/2            | 6350     | 11500            | 6900             | 1-7/8  | 3/4     | 15/16   | 7/8               | 15/16   | 9-1/8          |
| 5/8            | 6362     | 18500            | 11100            | 2-7/16 | 1       | 1-5/16  | 1-1/4             | 1-3/16  | 12-12/16       |
| 3/4            | 6375     | 31500            | 18900            | 2-7/8  | 1-1/4   | 1-5/8   | 1-3/8             | 1-1/2   | 14-11/16       |
| 3/4            | 6381     | 31500            | 18900            | 2-7/8  | 1-1/4   | 1-5/8   | 1-3/8             | 1-1/2   | 14-11/16       |
| 7/8            | 6387     | 33333            | 20000            | 3-5/8  | 1-23/32 | 2-27/32 | 1-5/8             | 1-13/16 | 18             |
| 1              | 6399     | 50000            | 30000            | 3-5/8  | 2       | 2-25/32 | 2                 | 2-1/8   | 19-7/8         |
| 1-1/4          | 63125    | 83333            | 50000            | 4-1/2  | 2-1/8   | 2-7/8   | 2-1/4             | 2-3/8   | 27-1/2         |
| 1-1/2          | 63150    | 116667           | 70000            | 5-3/8  | 2-1/4   | 3-1/8   | 2-1/4             | 2-3/8   | 31             |